


How to Save Millions Thru Repair and Maintenance Welding Technique

A. N. Reddy

GM- DOTES, Ador Fontech Ltd., Bangalore

The world has limited deposits of mineral resources. However, the depletion rate is resulting from increase in population, growth and development of industries, and consumption of raw materials that is on the rise. The consumption of new materials can be reduced by increasing the working life of components by recommending and implementing value added solutions. This will add further in reducing inventories, machinery down time and inventory costs. Therefore, reclamation and re-cycling of vital machinery components assumes high priority.

To suggest a suitable reclamation solution, the recommended electrode is to be deposited through a process called welding. Welding is defined as a process of joining two or more metals which are similar / dissimilar in nature, with or without flux, with or without filler so that the joint will be of homogenous in nature or superior to base metal properties. A typical weld along with its nomenclature is shown in **Fig. 1**.



Groove Weld Terminology
Fig. 1

Most of the parts one uses in any industry are of ferrous metals, hence, this author limits the discussions/solutions to ferrous metals only. When liquid metal solidifies from its melting point, structure will be crystalline - either BCC or FCC at room temperature. Metals shown in **Fig.2** have different atomic structures. These are shown in **Fig.2** and **Fig.3** as appropriate.








Fig. 3



Fe, Cr, V, W, Mo, Ta



Cu, Ni, Ag, Au, Mn



Cd, Zn, Ti, Co, Be

Fig. 2




Fig. 4




Fig. 5

When ferrous metal is subject to heat by welding what happens in the process to form HAZ of the base metal is clearly shown in **Fig. 4**.

The iron which is known also as allotropic metal occupies different crystalline structures at different temperatures and carbon percentages. This is given in **Fig. 5** below. There are mainly 3 phases for iron, i.e., ferritic structure which is soft, austenitic structure which is tough and martensitic structure which is hard. Whenever welding is carried out, base metal is of either ferritic or austenitic structure.

The iron which is known also as allotropic metal occupies different crystalline structures at different temperature and carbon percentages. This is given in **Fig. 5**. There are mainly 3 phases for iron, i.e., ferritic structure, which is soft, austenitic structure which is tough and martensitic structure which is hard. Whenever welding is carried out it has be when base metal is either in ferritic or austenitic structure.

A simplified version of carbon equilibrium diagram is shown in **Fig. 6** for better understanding.

Classification of Steels: For better understanding, steel is classified in to

1. Plain carbon steels
 - Low carbon steels : up to 0.30%C
 - Medium carbon steels: 0.30-0.60% C
 - High carbon steels: 0.60-1.70% C
2. Alloy steels
3. Stainless steels

When one comes across a steel component which has cracked/ worn out, it can be repaired instead of replacing with a new component (this will be 70-80% cheaper, better and faster compared to a new part) when one tries to do repair welding, one advises to use low heat input welding electrodes which will produce low heat input in to base metal, give high factor of




Fig. 6

safety and compatibility over wide variety of base metals such as low carbon steel, medium carbon steels, low alloy steels, high alloy steels, spring steels, manganese steels etc., For example, LH 106 is a low heat input welding electrode for SMAW process giving an UTS of 1,20,000 PSI and needs only 25-30 Amps of current for 1.6mm size.

For a successful reclamation of a component, one needs to follow correct procedure of welding depending on the type of base metal. When steel with carbon more than 0.3% is welded, it develops martensitic structure at the HAZ which is hard. Any hard structure, when load is applied, may develop cracks, and hence, failure is the result. Therefore pre-heating the job becomes very important. The following are the most important steps in successful welding of steels, alloy steels.

1. To pre-heat the base metal depending on its carbon equivalent.
2. To maintain inter-pass temperature below 200°C.
3. To post heat the job to 450°C and to slow cool to room temperature.

The welding rod selection should be nearest to base metal composition or alternatively higher range. Some of the jobs in different fields like cement, power mining, steel, paper, etc. are shown in Fig. 7 through Fig. 12 with considerable amount of savings for the benefit of the reader.

Table 1

Application	Crusher Shaft
Product	LH-106
Cost of Reclamation	Rs. 0.5 L
Approx. Savings	Rs. 1.5 L

Table 2

Application	Excavator Bucket
Product	LH-108/O-7020/P-7050
Cost of Reclamation	Rs. 1.2 L
Approx. Savings	Rs. 1.80 L

Table 3

Application	Excavator Bucket
Product	LH-713/Tubular Alloy 1
Cost of Reclamation	Rs. 1.50 L
Approx. Savings	Rs. 3.00 L

Table 4

Application	Kiln
Product	LH-104/LH-521
Cost of Reclamation	Rs. 10.00 L
Approx. Savings	Rs. 50.00 L

Table 6

Application	Support Roller
Product	LH-104/LH-128/LH-710
Cost of Reclamation	Rs. 3.50 L
Approx. Savings	Rs. 8.00 L

Table 5

Application	Base Metal	Product	Cost of reclamation
Thrust roller	Carbon steel	LH 104/LH710	RS.0.60L
Immersion tubes	SS 310	LH 126	RS.1.30L
Tip Casting	HK 40	LH 126/TA4CXX	RS. 3.50L
HIC Rotor	HK40	TA5	RS.0.80L
Feeder screws	Carbon steel	LH 720	RS.0.30L
Table liner plates	HC-HCr	LH 7450	RS.2.50L.
Compressor Piston	Al	LH 409	RS.0.20L




Fig. 7 : Refer Table 1




Fig. 10 : Refer Table 4



Fig. 8 : Refer Table 2




Fig. 11 : Refer Table 5



Fig. 9 : Refer Table 3




Fig. 12 : Refer Table 6